

LOCATION DATA

ID	Responsible Party	
H5-O10-25	City of Montrose	
Address Number	Street	
City	County	State
Northing	Easting	Verification Method
1660500.52	2322174.95	GPS - R8
Location Description		

**MANHOLE DATA**

Installed	Replaced	Retired	Total_Cost	Estimated_OCI	Estimated_OCR
1/1/1979	1/1/1979		148.83	29.37	Fair
Manufacturer	Cover Size	Cover Type	Surface Type	Manhole Size	Use Type
	24 Inches	Solid	Gravel	48 inch diameter	Wastewater
Lift Station	Hot Spot	Material	Pipe Material	Pipe Material Additional	Reline Date
No	No	Precast	VCP		
Pipe Size	Invert Elv	Depth to Invert	Rim to Invert	Num of Barrel Sec	Sec Issue from Top
12.00		16.70	16.20	4	
Outlet Direction	Outlet Diameter	Inlet Direction	Inlet Diameter	Inlet2 Direction	Inlet2 Diameter
W	12.00	E	12.00		
Inlet3 Direction	Inlet3 Diameter	Inlet4 Direction	Inlet4 Diameter	Inlet5 Direction	Inlet5 Diameter
Notes					

INSPECTION DATA

Task ID	Inspection ID	Status	Entered By	Inspection Date	Inspected OCI	Inspected OCR			
148749	192	Complete	cgerhardt	6/16/2020	29.37	Fair			
Flow Velocity	Flow Clarity	Service Inflow	Service Surcharge	Infil Inflow	Infil Surcharge	Infil Rate			
Steady	Clear Appearance	1	0	0	0				
Grease	Debris	Rats	Roaches	Spiders	Root	Cleaning	Reline	Maintenance	No Maintenance
0	0	0	0	0	0	1	1	1	0
Inspection Notes									