



Inspection report

Date: 4/1/2020	Work Order:	Weather:	Surveyed By: Tyler Good	Certificate Number: 1234	Pipe Segment Ref.: 297
Year laid:	Pre-cleaning:	Direction: Downstream	Pipe Joint Length:	Total Length: 295.1'	Length Surveyed: 295.1'

City: Montrose	Drainage Area:	Upstream MH: L9-26
Street: 1140 s townsend	Media Label:	Up Rim to Invert: 0.0
Location Code:	Flow Control:	Downstream MH: K9-6
Location Details:	Sheet Number:	Down Rim to Invert: 0.0
Pipe shape: Circular	Sewer Use:	Total gallons used: 0.0
Pipe size: 8"	Sewer Category: SEC	Joints passed: 0
Pipe material: Vitrified Clay Pipe	Purpose:	Joints failed: 0
Lining Method:	Owner:	

Additional Info:

1:2228	Distance	Code	Observation	Counter	Photo	Grade	
	0.00	AMH	Manhole / Start Inspection	00:00:00			
	0.00	MWL	Water Level, 5% of the vertical dimension	00:04:59			
	104.50	MMC	Material Change, Concrete pipe (non reinforced) / concrete?	00:07:17			
	207.87	MGP	General Photograph / needs lined?	00:09:41			
	295.14	AMH	Manhole / End Inspection	00:12:15			
QSR	QMR	SPR	MPR	OPR	SPRI	MPRI	OPRI
0000	0000	0.0	0.0	0.0	0.0	0.0	0.0



Section Pictures - 4/1/2020 - 297

City Montrose	Street 1140 s townsend	Date 4/1/2020	Pipe Segment Reference 297	Nr. 1
-------------------------	----------------------------------	-------------------------	--------------------------------------	-----------------



297_d008bb29-2bb9-4398-9bcc-6ca7ab575d7f_20200401_084001_202.jpg, 00:00:00, 0.00ft
Manhole



297_724ff749-2ddf-4bee-a7ff-cdeb8c31d9aa_20200401_084556_166.jpg, 00:04:59, 0.00ft
Water Level, 5% of the vertical dimension




Section Pictures - 4/1/2020 - 297

City Montrose	Street 1140 s townsend	Date 4/1/2020	Pipe Segment Reference 297	Nr. 1
-------------------------	----------------------------------	-------------------------	--------------------------------------	-----------------



297_6b63931e-ebdd-416f-9d6e-738ecb9f1062_20200401_084812_087.jpg, 00:07:17, 104.50ft
Material Change, Concrete pipe (non reinforced)



297_24bf6c94-8c3c-4a30-83bc-735eb4f0c968_20200401_084826_680.jpg, 00:07:17, 104.50ft
Material Change, Concrete pipe (non reinforced)



Section Pictures - 4/1/2020 - 297

City	Street	Date	Pipe Segment Reference	Nr.
Montrose	1140 s townsend	4/1/2020	297	1



297_1d0c3abe-9945-4fad-9928-6c1ddb29e7_20200401_085036_916.jpg,00:09:41,207.87ft
General Photograph



297_aa58ca28-abb8-429a-9c94-c33fbbba7cc6_20200401_085311_888.jpg,00:12:15,295.14ft
Manhole